

Q289 No Threads/
Clearance



Q34
Hub Stop




Required Parts

- 1 - Q289 No Threads/Clearance
- 1 - Q34 Hub Stop
- 1 - Q13 Hub
- 1 - X24 Set Screw
- 1 - Q18 Spring Lever
- 1 - Y42 Spring

Q13 Hub



Y42 Spring



X24 Set
Screw

Q18 Spring
Lever



**Presetup
LH Function**